

1423 Third Avenue, Suite 300 Seattle, Washington 98101 Phone 206.287.9130 Fax 206.287.9131

January 5, 2011

Sean Sheldrake Project Coordinator USEPA, Region 10 1200 Sixth Avenue, M/S ECL-111 Seattle, Washington 98101

Re: Progress Report for December 2010

Removal Action, Portland Harbor Superfund Site, NW Natural "Gasco" Facility

Project Number: 000029-02.26

Dear Mr. Sheldrake:

This monthly status report provides information required by the Removal Action Administrative Order on Consent (AOC) for the Portland Harbor Superfund Site, NW Natural "Gasco" Facility, in Oregon. EPA provided NW Natural with the Notice of Completion of Work under the AOC on December 14, 2010 so this is the final monthly status report that will be submitted pursuant to the AOC.

#### 1. ACTIONS TAKEN IN THIS MONTH

The following actions and correspondences occurred in this month:

- Submitted the November 2010 monthly progress report.
- Conducted the monthly visual monitoring of the pilot cap area.
- Receipt of EPA's Notice of Completion of Work under the AOC dated December 14, 2010. The Notice of Completion of Work identified the following list of post-removal site controls related to the AOC have been incorporated into the 2009 Administrative Settlement Agreement and Order on Consent for Removal Action (Order; docket number 10-2009-0255) entered into by NW Natural and Siltronic Corporation:
  - One additional bathymetric survey of the pilot cap area as part of a comprehensive bathymetric survey to be performed to support the final sediment remedy design for the overall site.

- Monthly visual monitoring (single day per month) of the shoreline area in the direct vicinity of the pilot cap to identify any areas of sheen or product release. The monthly visual monitoring shall continue until such time as the pilot cap area is addressed as part of the overall site remedy.
- If significant and/or unexpected river velocities occur, EPA may request additional activities to monitor the integrity and stability of the pilot cap, if necessary.
- Diver inspections on an annual basis or as agreed to with EPA for physical cap inspection for integrity.

#### 2. RESULTS OF SAMPLING, TESTS, AND OTHER DATA RECEIVED

The following results were received during this month:

- The visual monitoring survey did not identify any areas of sheen production, areas of erosion, or any other adverse issues within the removal action area.
- Copies of the visual monitoring survey reports extending from January to December 2010 are attached. All previous survey reports were submitted with previous annual monitoring reports completed under the AOC.

#### 3. SCHEDULE FOR THE NEXT MONTH

No future work will be completed under the AOC beyond payment of future response costs incurred under the AOC and record retention.

4. PROBLEMS ENCOUNTERED, ANTICIPATED DELAYS, AND SOLUTIONS No problems were encountered during this month.

If you have any questions, please contact Bob Wyatt at 503.226.4211, ext. 5425.

Sincerely,

Ryan Barth, P.E.

Anchor QEA, LLC

Ryan Baut

Cc: Matt McClincy, Oregon Department of Environmental Quality (ODEQ)
Dana Bayuk, ODEQ
Bob Wyatt, NW Natural
Patty Dost, Pearl Legal Group PC
Carl Stivers, Anchor QEA, LLC



Date January 21, 2010 **Project Number:** 000029-02 BG-21 Task 4 Location: NW Natural "Gasco" Site **Project Name:** NW Natural - Gasco **Monitoring Period:** Monthly(Year 4) – January 2010 Time **Time Observations** Observation Started: January 21, 2010 @ 08:00 Concluded: January 21, 2010 @ 16:00 Weather Partly cloudy, 54 degrees Fahrenheit, 0-7 knot winds from southeast during **Conditions:** pictures **Wave Action Observations:** Light wave action (0.0-0.1 feet in height) **Photographs** No Taken: Yes River level elevation on 01/21/10 ranged from 5.03 to 7.03 **Tidal Conditions:** feet; and approximately 5.63 feet at 14:30 when photos were taken (Datum: Morrison Gage Height) No erosion/deposition is evident along the shoreline. A 2-foot strip of organo-clay mat material was visible beneath the **Observations of Erosion/Deposition:** water surface near the shoreline at the upriver extent of the cap area (Photo 1).

Observations of Long-term Controls (i.e., oil booms, organo-clay mat, etc.)

During the Monitoring event, the Fuel and Marine Marketing (FAMM) oil boom was positioned across the cap area, between the upriver corner of the ship dock and the wooden dolphin (near the upriver extent of the site and near the Siltronic Corporation outfall). Buoys that identify the cap area to mariners were in place as installed. The position of the FAMM oil boom, warning buoys and a general overview of the site shoreline are shown in Photo 2.


#### Other Comments:

No sheen was observed in or around the cap area. Photo 3 shows the water surface and shoreline immediately downriver of the sediment cap. A ship (the Osprey Arrow) was docked along at the FAMM pier.



Photo 2 — FAMM oil boom and mariner warning buoys in place across pilot cap area (01/21/10):







**Date Project Number:** February 25, 2010 000029-02 BG-21 Task 4 Location: NW Natural "Gasco" Site **Project Name:** NW Natural - Gasco **Monitoring Period:** Monthly(Year 4) - February 2010 Time Observation **Time Observations** Started: February 25, 2010 @ 14:00 Concluded: February 25, 2010 @ 15:30 Weather **Conditions:** Cloudy, 52-57 degrees Fahrenheit, 0-3 knot winds from northwest **Wave Action Observations:** Light wave action (0.0-0.3 feet in height) **Photographs** No Taken: Yes Willamette River level on 02/25/10 ranged from 2.56 to 5.99 feet. The Willamette River level during photos is **Tidal Conditions:** approximately 5.88 feet at 14:45 (River Level Datum: Morrison Gage Height) No erosion/deposition is evident along the shoreline. Three segments of organo-clay mat material are visible beneath **Observations of Erosion/Deposition:** the water surface, one near the shoreline at the upriver extent of the cap area and the other two approximately 20 feet off the shoreline. (Photo 1).

Observations of Long-term Controls (i.e., oil booms, organo-clay mat, etc.)

The Fuel and Marine Marketing (FAMM) containment boom is positioned across the cap area, between the upriver corner of the ship dock and the wooden dolphin (near the upriver extent of the site and near the Siltronic Corporation outfall). Buoys that identify the cap area to mariners are in place as installed. The position of the FAMM oil boom, warning buoys and a general overview of the site shoreline are shown in Photo 2.


#### **Other Comments:**

No sheen is evident in or around the cap area. Photo 3 shows the water surface and shoreline immediately downriver of the sediment cap. A barge is docked at the riverward face of the FAMM pier.



Photo 2 - FAMM oil boom and mariner warning buoys in place across pilot cap area (02/25/10):







**Date Project Number:** March 18, 2010 000029-02 BG-21 Task 4

NW Natural Gasco Site,

7900 NW St. Helens Road, Location:

Portland, Oregon

**Project Name:** NW Natural - Gasco

**Monitoring Period:** Monthly(Year 4) - March 2010

Time

**Time Observations** 

Observation

Concluded: March 18, 2010 @ 15:00 March 18, 2010 @ 16:30

Weather

Started:

Conditions: Clear, 60-64 degrees Fahrenheit, 5-10 knot winds from northwest

**Wave Action** 

**Observations:** Moderate wave action (0.5-1.0 feet in height)

**Photographs** 

No Taken: Yes

Willamette River level on 3/18/10 ranged from 2.05 to **Tidal Conditions:** 

5.17 feet. The Willamette River level during photos is approximately 2.72 feet at 16:00 (River Level Datum:

Morrison Gage Height)

No erosion/deposition is evident along the shoreline. Three **Observations of Erosion/Deposition:** 

segments of organo-clay mat material are visible beneath

the water surface. (Photo 1).

**Observations of Long-term Controls** 

(i.e., oil booms, organo-clay mat, etc.)

The Fuel and Marine Marketing (FAMM) containment boom is positioned across the cap area between the upriver corner of the ship dock and the wooden dolphin (near the upriver extent of the site and near the Siltronic Corporation outfall). Buoys that identify the cap area to mariners are in place as installed. The position of the FAMM oil boom, warning buoys and a general overview of the site shoreline are

shown in Photo 2.

Other Comments:

No sheen is evident in or around the cap vicinity. Photo 3 shows the water surface and shoreline immediately downriver of the sediment cap.








Photo 2 — FAMM oil boom and warning buoys in place across pilot cap area (3/18/10):







**Date Project Number:** April 28, 2010 000029-02 BG-21 Task 4

NW Natural Gasco Site.

7900 NW St. Helens Road, Location:

Portland, Oregon

**Project Name:** NW Natural - Gasco

**Monitoring Period:** Monthly(Year 4) - April 2010

Time **Time Observations** 

Observation Started: Concluded: April 28, 2010 @ 12:45 April 28, 2010 @ 13:45

Weather Cloudy, intermittent rain showers, 50-55 degrees Fahrenheit, 5 knot wind from

**Conditions:** southeast

**Wave Action** 

**Observations:** Light wave action (0.1- 0.3 feet in height)

**Photographs** 

**Tidal Conditions:** 

Taken: No Yes

Willamette River level on 4/28/10 ranged from 5.38 to

8.16 feet. The Willamette River level during photos is approximately 5.84 feet (measured at 13:00, Vertical Datum:

Morrison Gage Height)

No erosion/deposition is evident along the shoreline of the **Observations of Erosion/Deposition:** 

capped area. Two segments of organo-clay mat material are

visible beneath the water surface (Photo 1).

**Observations of Long-term Controls** 

(i.e., oil booms, organo-clay mat, etc.)

The Fuel and Marine Marketing (FAMM) containment boom is positioned across the cap area between the upriver corner of the ship dock and the wooden dolphin (near the upriver extent of the site and near the Siltronic Corporation outfall). Buoys that identify the cap area to mariners are in place as installed. The position of the FAMM oil boom, warning buoys and a general overview of the site shoreline are

shown in Photo 2.

Other Comments:

No sheen is evident in or around the cap vicinity. Photo 3 shows the water surface and shoreline immediately downriver of the sediment cap.







Photo 2 — FAMM oil boom and mariner warning buoys in place across pilot cap area (04/28/10):







**Project Number:** Date May 17, 2010 000029-02 BG-21 Task 4

Location: NW Natural "Gasco" Site

**Project Name:** NW Natural - Gasco

**Monitoring Period:** Monthly(Year 4) - May 2010

Time

**Time Observations** Observation

Started: May 17, 2010 @ 13:30 Concluded: May 17, 2010 @ 15:30

Weather

**Conditions:** Clear, 72 degrees Fahrenheit, 0-3 knot winds from northwest

**Wave Action** 

**Observations:** Light wave action (0.1-0.3 feet in height)

**Photographs** 

**Tidal Conditions:** 

No Taken: Yes

**Observations of Erosion/Deposition:** 

Willamette River level on 05/17/10 ranged from 4.33 to 6.88

feet. The Willamette River level during photos is approximately 5.05 feet measured at 14:30 (River Level

Datum: Morrison Gage Height)

No erosion/deposition is evident along the shoreline. Three

sections of organo-clay mat material are visible beneath the water surface. One exposed section of organo-clay mat is visible at the upriver extent of the cap area extending from 2 feet to 10 feet channelward of the water's edge. Two exposed sections of exposed organo-clay mat are visible

approximately 1-2 feet channelward of the water's edge, one near the midpoint of the cap area and the second near its

The Fuel and Marine Marketing (FAMM) containment boom

downriver extent. (Photo 1).


**Observations of Long-term Controls** 


is positioned across the cap area, between the upriver corner of the ship dock and the wooden dolphin (near the upriver extent of the site and near the Siltronic Corporation (i.e., oil booms, organo-clay mat, etc.) outfall). Buoys that identify the cap area to mariners are in place as installed. The position of the FAMM oil boom, warning buoys and a general overview of the site shoreline


are shown in Photo 2.


**Other Comments:** 

No sheen is evident in or around the cap area. Photo 3 shows the water surface and shoreline immediately downriver of the sediment cap. A barge is docked at the riverward face of the ship dock.












**Date Project Number:** June 17, 2010 000029-02 BG-21 Task 4 Location: NW Natural "Gasco" Site **Project Name:** NW Natural - Gasco **Monitoring Period:** Monthly(Year 4) - June 2010 Time Observation **Time Observations** June 17, 2010 @ 11:00 June 17, 2010 @ 14:00 Started: Concluded: Weather **Conditions:** Cloudy, mid 60s degrees Fahrenheit, 3-5 knot winds from the north **Wave Action Observations:** Light wave action (0.2-0.4 feet in height) **Photographs** No Taken: Yes Willamette River level on 06/17/10 ranged from 10.68 to 11.19 feet. The Willamette River level during photos is **Tidal Conditions:** approximately 11.04 feet measured at 11:15 am (River Level Datum: Morrison Gage Height) No erosion/deposition is evident along the shoreline. Due to high river water levels, the exposed organo- clay mat **Observations of Erosion/Deposition:** material observed in preceding events was not visible (Photo 1). The Fuel and Marine Marketing (FAMM) containment boom is positioned across the cap area, between the upriver corner of the ship dock and the wooden dolphin (near the **Observations of Long-term Controls** upriver extent of the site and near the Siltronic Corporation (i.e., oil booms, organo-clay mat, etc.) outfall). Buoys that identify the cap area to mariners are in place as installed. The position of the FAMM oil boom, warning buoys and a general overview of the site shoreline are shown in Photo 2.

#### **Other Comments:**


No sheen is evident in or around the cap area. Photo 3 shows the water surface and shoreline immediately downriver of the sediment cap. A barge is docked at the riverward face of the ship dock.



Photo 1 - High river level shown above the extent of sediment cap (06/17/10):









**Date** <u>July 16, 2010</u> **Project Number:** <u>000029-02 BG-21 Task 4</u>

Location: NW Natural "Gasco" Site

Project Name: NW Natural – Gasco

Monitoring Period: Monthly(Year 4) – July 2010

Time

Time Observations Observation

Started: <u>July 16, 2010 @ 12:30</u> **Concluded:** <u>July 16, 2010 @ 14:00</u>

Weather

**Conditions:** Clear, 75 degrees Fahrenheit, 0-3 knot winds from northwest

**Wave Action** 

**Observations:** Light wave action (0.0-0.3 feet in height)

**Photographs** 

**Tidal Conditions:** 

Taken: (Yes) No

**Observations of Erosion/Deposition:** 

**Observations of Long-term Controls** 

(i.e., oil booms, organo-clay mat, etc.)

Willamette River level on 07/16/10 ranged from 3.72 to 6.60

feet. The Willamette River level during photos is approximately 4.98 feet measured at 13:00 (River Level

Datum: Morrison Gage Height).

No erosion/deposition is evident along the shoreline. Three

sections of organo-clay mat material are visible beneath the water surface. One exposed section of organo-clay mat is visible at the upriver extent of the cap area extending from 2 feet to 10 feet channelward of the water's edge. Two exposed sections of exposed organo-clay mat are visible

approximately 1-2 feet channelward of the water's edge, one near the midpoint of the cap area and the second near its

near the midpoint of the cap area and the second near its

downriver extent. (Photo 1).

The Fuel and Marine Marketing (FAMM) containment boom is positioned across the cap area, between the upriver

corner of the ship dock and the wooden dolphin (near the upriver extent of the site and near the Siltronic Corporation outfall). Buoys that identify the cap area to mariners are in place as installed. The position of the FAMM oil boom,

warning buoys and a general overview of the site shoreline


are shown in Photo 2.

Other Comments:


No sheen is evident at or near the cap area. Photo 3 shows the water surface and shoreline immediately downriver of the sediment cap.













 Date
 August 17, 2010
 Project Number:
 000029-02 BG-21 Task 4

Location: NW Natural "Gasco" Site

Project Name: <u>NW Natural – Gasco</u>

Monitoring Period: Monthly(Year 4) – August 2010

Time Observations Observation

**Started:** August 17, 2010 @ 15:00 **Concluded:** August 17, 2010, 16:30

Weather

**Conditions:** Mostly Cloudy, Humid, 90° Fahrenheit, 3-5 knot wind from the north

**Wave Action** 

**Observations:** Light wave action (0.2 - 0.5 feet in height)

**Photographs** 

**Tidal Conditions:** 

Taken: (Yes) No

Willamette River level on 08/17/10 ranged from 1.66 to 5.17

feet. The Willamette River level during photos is approximately 2.43 feet measured at 15:30 (River Level

Datum: Morrison Gage Height).

No erosion/deposition is evident along the shoreline. Three

sections of organo-clay mat material are on the beach along the shoreline. One exposed section of organo-clay mat is visible at the upriver extent of the cap area extending from the river's shoreline to 10 feet out of the water. Two exposed sections of exposed organo-clay mat are visible

near the midpoint of the cap area, one 3 foot in length, the other about 18 inches. The last exposed mat is near the downriver side, along the shoreline, approximately 30 feet

long. (Photo 1).

The Euclie

Observations of Long-term Controls (i.e., oil booms, organo-clay mat, etc.)

**Observations of Erosion/Deposition:** 

The Fuel and Marine Marketing (FAMM) containment boom is positioned across the cap area, between the upriver corner of the ship dock and the wooden dolphin (near the upriver extent of the site and near the Siltronic Corporation outfall). Buoys that identify the cap area to mariners are in place as installed. The position of the FAMM oil boom, warning buoys and a general overview of the site shoreline

are shown in Photo 2.

Other Comments:

No sheen is evident in or around the cap area. Photo 3 shows the water surface and shoreline immediately downriver of the sediment cap.



Photo 2 — FAMM oil boom and mariner warning buoys in place across pilot cap area (08/17/10):







 Date
 September 21, 2010
 Project Number:
 000029-02 BG-21 Task 4

Location: NW Natural "Gasco" Site

Project Name: <u>NW Natural – Gasco</u>

Monitoring Period: Monthly(Year 4) – September 2010

Time

**Time Observations** 

Observation

Started: Sept. 21, 2010 @ 13:30 Concluded: Sept. 21, 2010 @ 14:30

Weather

**Conditions:** Partly Cloudy, 60s° Fahrenheit, 0-3 knot winds from the north

**Wave Action** 

**Observations:** Light wave action (0.2 - 0.4 feet in height)

**Photographs** 

**Tidal Conditions:** 

Taken: Yes No

Willamette River level on 09/21/10 ranged from 0.67 to 4.19

feet. The Willamette River level during photos is approximately 0.76 feet measured at 14:00 (River Level

Datum: Morrison Gage Height).

No erosion/deposition is evident along the shoreline. All

visible organo-clay mat material segments are out of the water. One exposed section of organo-clay mat is visible at the upriver extent of the cap area is approximately 15 feet long and 2 feet from the water's edge. Two exposed

sections of exposed organo-clay mat are visible near the midpoint, head of the cap area, one 4 foot in length, the other about 2 feet. The last exposed mat is near the downriver side, 4 feet from the shoreline, approximately 30

feet long. (Photo 1).

downriver side, 4 feet leng. (Photo 1

Observations of Long-term Controls (i.e., oil booms, organo-clay mat, etc.)

**Observations of Erosion/Deposition:** 

The Fuel and Marine Marketing (FAMM) containment boom is positioned across the cap area, between the upriver corner of the ship dock and the wooden dolphin (near the upriver extent of the site and near the Siltronic Corporation outfall). Buoys that identify the cap area to mariners are in place as installed. The position of the FAMM oil boom, warning buoys and a general overview of the site shoreline

are shown in Photo 2.


Other Comments:


No sheen is evident in or around the cap area. Photo 3 shows the water surface and shoreline immediately downriver of the sediment cap.

Photo 1-Exposed section of organo-clay mat 4 feet from the shoreline near downriver end of cap (09/21/10):



Photo 2 — FAMM oil boom and mariner-warning buoys in place across pilot cap area (09/21/10):







 Date
 October 21, 2010
 Project Number:
 000029-02 BG-27 Task 4

Location: NW Natural "Gasco" Site

Project Name: NW Natural – Gasco

Monitoring Period: Monthly(Year 4) – October 2010

Time Observation

Time Observations

**Started:** Oct. 21, 2010 @ 13:15

13:15 **Concluded:** Oct. 21, 2010 @ 14:45

Weather

**Conditions:** Mostly Cloudy, 60s° Fahrenheit, winds calm

**Wave Action** 

**Observations:** Very light wave action (0.0 - 0.2 feet in height)

**Photographs** 

Tidal Conditions:

Taken: Yes No

Willamette River level on 10/21/10 ranged from 0.97 to 4.46

feet. The Willamette River level during photos is approximately 1.13 feet measured at 13:45 (River Level

Datum: Morrison Gage Height).

No erosion/deposition is evident along the shoreline. All

visible organo-clay mat material segments are out of the water. One exposed section of organo-clay mat is visible at the upriver extent of the cap area is approximately 15 feet long and 2 at the water's edge. Two exposed sections of exposed organo-clay mat are visible near the midpoint, head of the cap area, one 4 foot in length, the other about 2 feet.

The last exposed mat is near the downriver side, 4 feet from

the shoreline, approximately 30 feet long. (Photo 1).

Observations of Long-term Controls

corner of the ship dock and the wood turniver systems of the site and poor the ship dock and the wood turniver systems of the site and poor the ship dock and the wood turniver systems of the ship dock and the wood turniver s

Observations of Long-term Controls (i.e., oil booms, organo-clay mat, etc.)

**Observations of Erosion/Deposition:** 

The Fuel and Marine Marketing (FAMM) containment boom is positioned across the cap area, between the upriver corner of the ship dock and the wooden dolphin (near the upriver extent of the site and near the Siltronic Corporation outfall). Buoys that identify the cap area to mariners are in place as installed. The position of the FAMM oil boom, warning buoys and a general overview of the site shoreline

are shown in Photo 2.


Other Comments:


No sheen is evident in or around the cap area. Photo 3 shows the water surface and shoreline immediately downriver of the sediment cap.

Photo 1-Exposed section of organo-clay mat 15 feet long extends to the river's edge at the upriver extent of cap (10/21/10):



Photo 2 - FAMM oil boom and mariner warning buoys in place across pilot cap area (10/21/10):







 Date
 November 22, 2010
 Project Number:
 000029-02 BG-27 Task 4

Location: NW Natural "Gasco" Site

Project Name: <u>NW Natural – Gasco</u>

Monitoring Period: Monthly(Year 4) – November 2010

Time

**Time Observations** 

Observation

**Started:** Nov. 22, 2010@ 13:30

**Concluded:** Nov. 22, 2010 @ 15:00

Weather

**Conditions:** Rain, 39° Fahrenheit, winds light from SE

**Wave Action** 

**Observations:** Light wave action (0.1 - 0.3 feet in height)

Yes

**Photographs** 

**Tidal Conditions:** 

Taken:

No

Willamette River level on 11/22/10 ranged from 4.22 to 7.14

feet. The Willamette River level during photos is approximately 4.46 feet measured at 14:00 (River Level

Datum: Morrison Gage Height).

No erosion/deposition is evident along the shoreline. The

visible organo-clay mat segments are partially submerged. Approximately 3 feet of organo-clay mat is visible at the upriver extent of the cap. One exposed section of exposed organo-clay mat measuring 4 foot in length is visible approximately 2 feet from the river's edge. The last exposed

organoclay mat is approximately 20 feet long located near

the downriver extent of the cap, and submerged in

approximately1.5 feet of water,. (Photo 1).

Observations of Long-term Controls (i.e., oil booms, organo-clay mat, etc.)

**Observations of Erosion/Deposition:** 

The Fuel and Marine Marketing (FAMM) containment boom is positioned across the cap area, between the upriver corner of the ship dock and the wooden dolphin (near the upriver extent of the site and near the Siltronic Corporation outfall). Buoys that identify the cap area to mariners are in place as installed. The position of the FAMM oil boom, warning buoys and a general overview of the site shoreline is shown in Photo 2.

Other Comments:

No sheen is evident in or around the cap area. Photo 3 shows the water surface and shoreline immediately downriver of the sediment cap.

Photo 1-V is ible section of organo-clay mat 20 feet long in 1.5 feet of water on the downriver end of cap (11/22/10):



Photo 2 - FAMM oil boom and mariner warning buoys in place across pilot cap area (11/22/10):







**Date Project Number:** December 20, 2010 000029-02 BG-27 Task 4

Location: NW Natural "Gasco" Site

**Project Name:** NW Natural - Gasco

**Monitoring Period:** Monthly(Year 4) – December 2010

Time

**Time Observations** 

Observation

Started: December 20, 2010 @ 14:00 Concluded: December 20, 2010 @ 16:00

Weather

**Conditions:** Cloudy, low 40s degrees Fahrenheit, 2-5 knot winds from the south

**Wave Action** 

Observations: Mid wave action (0.3-0.6 feet in height)

**Photographs** 

**Tidal Conditions:** 

No Taken: Yes

Willamette River level on 12/20/10 ranged from 8.20 to 6.60

feet. The Willamette River level during photos is

approximately 7.71 feet measured at 15:00 (River Level

Datum: Morrison Gage Height)

No erosion/deposition is evident along the shoreline. Due to

high river water levels, the exposed organo- clay mat material observed in preceding events was not visible

**Observations of Erosion/Deposition:** 

(Photo 1).

**Observations of Long-term Controls** 

(i.e., oil booms, organo-clay mat, etc.)

The Fuel and Marine Marketing (FAMM) containment boom is positioned across the cap area, between the upriver corner of the ship dock and the wooden dolphin (near the upriver extent of the site and near the Siltronic Corporation outfall). Buoys that identify the cap area to mariners are in place as installed. The position of the FAMM oil boom, warning buoys and a general overview of the site shoreline

are shown in Photo 2.

Other Comments:

No sheen is evident in or around the cap area. Photo 3 shows the water surface and shoreline immediately downriver of the sediment cap.






Photo 2 — FAMM oil boom and mariner warning buoys in place across pilot cap area (12/20/10):



